



Overview: Part of spill impact on 24" Npoku-Bomu Trans Niger pipeline right of way at Biara. Picture was taken during Joint Investigation of 11th August 2013.



Close up: Drilled hole on 24" Npoku-Bomu Trans Niger pipeline at Biara. Picture was taken during Joint Investigation of 11th August 2013.