



Overview: Part of spill impact on 24" Nkpoku-Bomu Trans Niger pipeline right of way at Bera. Picture was taken during Joint Investigation of 20th August 2013.



Close up: Drilled hole on 24" Nkpoku-Bomu Trans Niger pipeline at Bera. Picture was taken during Joint Investigation of 20th August 2013.