



Overview: Part of spill impact on 10" Ekulama1 – Sanbarth Pipeline right of way at Ekulama. Picture was taken during Joint Investigation of 29th August 2013.



Close-up: Spill due to corrosion on 10" Ekulama1 – Sanbarth Pipeline at Ekulama. Picture was taken during Joint Investigation of 25th October 2013.