



Close up: Damage from heavy equipment on 4" Cawthorne Channel Well51T flowline at Mbiama. Picture was taken during Joint Investigation of 21st August 2013.