



Overview: Part of spill impact on 24" Bomu-Bonny Trans Niger Pipeline right of way at Mogho. Picture was taken during Joint Investigation of 1st January 2014.



Close-up: Hacksaw cut on 24" Bomu-Bonny Trans Niger Pipeline at Mogho. Picture was taken during Joint Investigation of 1st January 2014.