JOINT INVESTIGATION REPORT FOR INCIDENT NO: 108 4422 JIV report S	S/N: 0451
---	-----------

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

•	·		
A. GENERAL INFORMATION:			
1. Spill incident Number: 10844	22 2.Typ	e of incident* OIL SPILL	
3. Name of Location SEIBOU	BULKLINE	3 AT AZARGBENE	
4. Name of nearest community AZARG	BENE 5. State: BA	YELSA 6. LGA EKEREMOR	
7. Type of Production facility/Installation			
B. INCIDENT INFORMATION:			
9. Details of incident  a. Date of incident:  b. Start date/time of investigation:  c. Investigation End date:  d. Description of spill point environn    Firmed soil	TH DECEMBER 2013 Actual inv	estigation duration, days: 2 DAYS	
Under water	Swampy	Exposed pipe surface	
Well Platform (on Water)		☐Drill Rig	
e. Description of leak point (tick as a  Drilled hole	ppiicable);  Hack saw cut	Tear ().	
Complete Rupture	☐ Inward dent,	Well head tampering	
Failed Weld-on illegal hot tap valv	•	Missing Pipeline/Flowline	
Crude oil theft (illegal bunkerin		☐ Third party tampering with Clamp	
☐ Third party tampering with valv		☐ Third party tampering with flange,	
Corrosion	☐Saver-pit over flow.	<u> </u>	
Bulging Outward	-	wall failure Accidental 3 <sup>rd</sup> party	•
equipment impact LIValv	e Failure	□com unit failure □Cold vent	
Relief valve failure	Others (specify) FF	THE AT 12 O'CLOCK POSITIONS	Γ - 7 <b>7</b>
f. Incident caused by:  Third party interference (Sabotage)	T	neOT: A seidental 2 <sup>rd</sup> morty democra <sup>©</sup> l\	
	ncluding Mystery spills)	end, Accidentar 5 party damaged)	
Lioperational Liousers (1	caung mystery spins)		
g. Spill point coordinates		(-0 0-16)	
Measuring unit METER!	MUNHA	(WEST BELT)	
Northing:		Easting:	
SPILL POINT 1: 9		7	
SPILL POINT 2:	17833.60	380687.94	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: $1084422$ JIV report S/N: $045$	51
---	----

				•				
). R	ISK ASSESSME	NT						
	10. Type	of environment:						
	□ Land	<b>⊠</b> Swamp	□wa	ter	Seasonal swa	ւութ <b>ြ</b> Sho	oreline/Wate	erfront
	i. Type o	of environment to	which oil	has spread:				
	Land	Swamp	₩a	ter	□River (identi	fy)		
	ii. Weath	er condition						
1	Rain 1. Distance from t	Sunny he nearest sensiti	□Dr) ve habitat		et 🔲 Win	ıdy	□Hot	Cool
	☐ Governmen ☐ Drinking w ☐ Built up are ☐ Farmlands ☐ Fish Farm/ ☐ Fishing net ☐ Others (spe	ea Pond t	esignated	protected ar	ea [ [ [ [ [	[m, [m, [m, [m, [m,	HON! THE	E MITH VICINI
1	12. Containment m	easures put in pla	ice;					
	Booms Others:	Trench	□Dy	ke	□Natural depr	ession	□Pit	
	13. Any pictures or	video coverage?	,		N/	[N]		
	14. Was there any	disruption to the	investigati	on?	.[Y]	[14]		
If ye	s give brief descript	tion:						
	N	01	AF	PLI	CABL	E	· <del>*</del>	<u></u>
D. 1	YPE/NUMBERS	OF PROPERTI	ES, IF A	ny, foun	D WITHIN TE	E AREA	OF SPRE	AD OF OIL
	15. Structures / P							
S/N	Type of Struct	ures Descri	ption S	ize	Number	<del>.</del>	Comment	5
	I				<u> </u>		<u> </u>	

S/N	Type of Structures	Description	Size	Number	Comments
•		<u> </u>			
	NONE W	LAHA	AR	A OF	MART
			<u> </u>		

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1084422 JIV report S/N: 0451

S/N	Type of crops MANGROVES	Young	Medium	Matured	Quantity	Comments
<u> </u>	MANGROVES	36	69	_114	219	
ļ. <u> </u>						
<b></b>	<del>                                     </del>					
-						
		<del>-/</del>	/			
		<del></del>				<u> </u>

#### 17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	NONE WI	THIN AREA	OF IMP	ACT

18. Others (Specify) i.e. Animal Traps


S/N	Others	Description	Quantity/Size	Comments
	MONE	INTHIN A	REA OF IN	PACT
	<u>.</u>		- 1, 0, 1,	PACI

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

FAILED 2" WELD-ON ILLEGAL HOT-TAP NIPPLE AT 12 O'LLOCK POSITION



FMLED 2" WELD-ON ILLEGAL HOT-TAP MIPPLE AT 12 O'CLOCK POSITION



SEIBM BULKLINE 3 AT AZARGRENE

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1084422 JIV report S/N: 0451

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

S/N	Northing	Easting
		Cobrantes
		ZYP.
		86
		(0)
		0
	× ×	
	2	
	1	
	1	
	L. L.	

#### G. INCIDENT INFORMATION:

70	T		<b>A</b>	The
ZU	m	nacteo	Апея	Details
			+ 64 444	**************************************

•	Total calculated area of impact_	111463.04 m <sup>2</sup>
	Impact within SPDC R.O.W	
•	Impact outside SPDC R.O.W	44117 m

21. Volume of oil recovered before completion of JIV (VreeJ):

		<u>.                                    </u>	Recovered	oil V <sub>ree3</sub> :	NIL_	Barrels
22 Co	mnutation o	f ectimated re	sidual volume	on cita		
	mputation of	estimated volu	me of pool of fre	e phase oil (on lan	d or confined water	_body).
	i. Ar	ea (m²) occupie	d by pool of free	phase oil	39.77 m	<del></del>
			T	phase oil	007W	
		ulsification fac		<u> </u>		
	iv.	Estimated '	Volume of pool	of free phase oil.	9 0 0	- barre
			V <sub>pool</sub> :	<u> </u>	8.35	
b. Co	mputation of	estimated volu	me of infiltrated	oil in the soil (V <sub>inf</sub> )	) <u>.</u>	
			filtrated oil at sp		•	
	i. Ar	ea* (m²) of soil	covered by the o	il: e.	E	
		-	•	~ 3451	/flowline:	,
		il type:	_C)		y of the soil)	
	v. Ca	use of spill	1 1	. Oil type:	<u></u>	
		Residence time		·		
	viii. Av	erage depth of i	nfiltration below	leaking facility i.e	. pipeline/flowline:	<b>:</b>
		•	finfiltration arou		•	
	<b>x</b>					
		Estimated (6)	<u> </u>	Sales House Head	MIL NIL	_ вап
	2. Estimate	d Volume of int	filtrated oil at sec	ond spill point [if	applicable] (Vinf b	)
	i. An	a* (m²) of soil	covered by the o	il·		
•			•	acility i.e. pipeline	/flowline	
			_	(effective perdit		<del></del>
		se of spill:	- 18	Off type:	,	
	vii. Oil	Residence time	on site, day:			
		NI J		leaking facility i.e	. pipeline/flowline:	
		• -	infiltration arou			
		A TRACT			NIL	barreis
:	3. E	a de la companya de l		A Billion	<u> </u>	
	stimated	Volume of infil	trated oil outside	immediate spill p	opp(s) regilir (Vinf	(c)
			overed by the oil	D.	BL	
	ii. Are	a (m²) of the po	ol of free phase	is couch with se	oik:	
	iii. Avo	tage Depth (m)	below ground s	urface of infiltratio	e of oil:	
		sped D				
	v. <i>P</i> e	cffective posos	ity of the soil)	·		
	vi.			WINSA A V	MI	f be

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1084422 JIV report S/N: 0451

ii. Table of average depth of oil on water based on coloration (

\*\*Spill Factors from USCG FOG (2000 Edition)

•	Thickness _(mm)	Percentage coverage	Volume (ni3)
Barely Visible	0.00004		
Silvery	0.00008	45 %	0.0040
Slight Color	0.00015	10 7.	0.0016
Bright Color	0.0003		
Dull	0.001	15%	0.0165
Dark	0.002		
Black oil	0.1	15 %	1.6470
Emulsion (30% Oil)	i	15 %	4.9411

	Percent Total	100%		
iii.	Estimated Volume	of oil on open water. Vwa:	41.58	Barrels

### 24. Calculation of evaporated volume:

- i. Estimated Volume available for evaporation within surface area: 49.93 BBLC
- ii. E-Factor: 15 %.

iii. Estimated Volume of evaporated oil. V<sub>evap</sub>: 8.8/ Barrels

Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium	
Oil Residence time	< 1 day	10%	5%	
	1-7 days	25%	15%	
	> 7 days	40%	25%	

			7 + 8.	¥=5	P. Wille
Estimated Repor	ted Volume** V <sub>es</sub> (bb	59 B	BLS		

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m<sup>3</sup> to barrels is Volume (m3) x 6.29; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of | bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

#### 26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1084422 JIV report S/N: 0451

B. Investigation of the incident site showed that there is residual impact on site requiring further works

#### 27. REPRESENTATIVES

This report was filled, agreed and signed on the 10 421 12 /20 2 by joint investigation representatives from


- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]: 
   □
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

### 28. Appendix 1: Overview sketch of the site

Location :	 		<del></del> -	
	 		<del>-</del>	
		·		i

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1084422 JIV report S/N: 0451



**SPILL POINT** 

East North

380687.94,97833.6

**WEST-BELT** 

AREA 2(LIGHT IMPACT ON WATER

East

North 381276.618 ,98083.360

381200.645 ,98089.657

381288.895 ,98149.477

381292.763 ,98165.126

381303.442,98184.756

381324.221,98202.319

381384.376,98148.038

381399,942,98093.281

381435.711 ,98052.988

381393.197,98056.696

381384.876,98085.629

381355.161,98140.530

381300.600 ,98106.691

381276.618 ,98083.360

#### AREA 1(LIGHT IMPACT ON WATER

East North

381752.783,98187.100

381821.429,98166.488

381756.550,98105.386

381724.111,98090.110

381680.222,98036.646

381598.170,98025.190

381551.903,98003.495

381438.901,98007.148

381296.599,98031.771

381177.321,98062.474

381026.637,98066.577

380858.120,97975.548

380764.431,97857.462

380727.355,97770.796

380672.719,97713.538 380600.514,97585.458

380587.961,97550.284

380596.600,97506.668

380585.121,97300.965

380558-325,97266.718

380529.275,97137.492

380562.223,97008.822

380607.801,96942.072

380689.730,96889.983

380712.448,96885.076

380758.871,96890.347 380767.310,96848.883 380733.871,96829.641 380668.798,96862.582 380555.308,96936.256 380526.867,96973.624 380485.752,97080.708 380492.194,97115.107 380487.237,97150.593 380486.166,97161.362 380517.095,97221.231 380559.946,97364.933 380552.581,97484.824 380558,429,97551.076 380583.446,97663.196 380638.783,97749.120 380655.451,97785.808 380684.900,97815.160 380727.816,97859.088 380730.325,97863.181 380782.407,97948.151 380786.682,97954.254 380809.725,97970.671 380832.177,97993.331 380941.656,98068.169 381066.710.98101.884 381114.651,98101.233 381153.521,98085.671 381200.645,98089.657 381276,618,98083.360 381279.649,98065.331 381365.854,98045.975 381383.205,98048.697 381393.197,98056.696 381435.711,98052.988 381489.230,98038.063 381650.523,98106.848 381752.783,98187.100 The Early Control (1955)

### AREA 3(FREE PHASE CRUDE OIL IMPACT

East North
380675.500,97835.460
380680.400,97849.690
380685.100,97862.880
380690.100,97877.090
380730.325,97863.181
380727.816,97859.088
380684.900,97815.160