



Overview: Part of spill impact on Ubie Well4S Wellhead right of way at Idukepuye. Picture was taken during Joint Investigation of 19th December 2013.



Close-up: Crude oil theft point on Ubie Well4S Wellhead at Idukepuye. Picture was taken during Joint Investigation of 19th December 2013.