



Overview: Part of spill impact on 20" Otumara – Escravos Pipeline right of way at Ugboegungun. Picture was taken during Joint Investigation of 18th December 2013.



Close-up: Illegal fitting on 20" Otumara – Escravos Pipeline at Ugboegungun. Picture was taken during Joint Investigation of 18th December 2013.