



Overview: Part of spill impact on 16" Nunriver – Kolocreek Pipeline right of way at Oporoma. Picture was taken during Joint Investigation of 29th December 2013.



Close-up: Hacksaw cut on 16" Nunriver – Kolocreek Pipeline at Oporoma. Picture was taken during Joint Investigation of 29th December 2013.