



Overview: Part of spill impact on 12" Oguta – Egbema Pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 29th December 2013.



Close-up: Illegal fitting on 12" Oguta – Egbema Pipeline at Obiakpu. Picture was taken during Joint Investigation of 29th December 2013.