



Overview: Part of spill impact on Seibou Bulkline3 right of way at Azargbene. Picture was taken during Joint Investigation of 20th December 2013.



Close-up: Illegal fitting on Seibou Bulkline3 at Azargbene. Picture was taken during Joint Investigation of 20th December 2013.