



Overview: Part of spill impact on 20" Otumara - Escravos Pipeline right of way at Ogidigben. Picture was taken during Joint Investigation of 11th December 2013.



Close-up: Illegal fitting on 20" Otumara - Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 11th December 2013.



Close-up: Illegal fitting on 20" Otumara - Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 11<sup>th</sup> December 2013.