



Overview: Part of spill impact on 28" Nkpoku – Bomu Pipeline right of way at B-Dere. Picture was taken during Joint Investigation of 31st December 2013.



Close-up: Hacksaw cut on 28" Nkpoku – Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 31st December 2013.