



Overview: Part of spill impact on 8" Obigbo North – Ogale Pipeline right of way at Umosoya. Picture shows sandbags and tarpaulin left behind by unknown persons. Picture was taken during Joint Investigation of 11th December 2013.



Overview: Part of spill impact on 8" Obigbo North – Ogale Pipeline right of way at Umosoya. Picture was taken during Joint Investigation of 11th December 2013.



Close-up: Illegal fittings on 8" Obigbo North – Ogale Pipeline at Umosoya. Picture was taken during Joint Investigation of 11th December 2013.