



Close-up: Illegal fitting on 6" Awoba flowstation Manifold Pipeline at Awoba. Picture was taken during Joint Investigation of 3rd December 2013.