



Overview: Part of spill impact on 24" Nkpoku – Bomu Pipeline right of way at Kpите. Picture was taken during Joint Investigation of 31st December 2013.



Close-up: Hacksaw cut on 24" Nkpoku – Bomu Pipeline at Kpите. Picture was taken during Joint Investigation of 31st December 2013.