



Overview: Part of spill impact on 36" Nkpoku-Bomu Pipeline right of way at Agbonchia. Picture was taken during Joint Investigation of 14th December 2013.



Close-up: Illegal fittings on 36" Nkpoku-Bomu Pipeline at Agbonchia. Picture was taken during Joint Investigation of 14th December 2013.