



Overview: Part of spill impact on Nembe 2 Well17S flowline right of way at Nembe. Picture was taken during Joint Investigation of 27<sup>th</sup> February 2013.



Close up: Cut flowline section on Nembe 2 Well17S flowline at Nembe. Picture was taken during Joint Investigation of 27<sup>th</sup> February 2013.



Close up: Missing flowline section on Nembe 2 Well17S flowline at Nembe. Picture was taken during Joint Investigation of 27<sup>th</sup> February 2013.