



Overview: Part of spill impact on 10" Ekulama-Sanbarth pipeline right of way at New Town. Picture was taken during Joint Investigation of 17th February 2013.



Close up: Ground off welding joint on 10" Ekulama-Sanbarth pipeline at New Town. Picture was taken during Joint Investigation of 17th February 2013.