



Overview: Part of spill impact on 18" Assa-Rumuekpe pipeline right of way at Elele-Alimini. Picture was taken during Joint Investigation of 26<sup>th</sup> February 2013.



Close up: Illegal fittings on 18" Assa-Rumuekpe pipeline at Elele-Alimini. Picture was taken during Joint Investigation of 26<sup>th</sup> February 2013.