



Overview: Part of spill impact on 4" Awoba North West Well L & S flowlines right of way at Boro. Picture was taken during Joint Investigation of 4th March 2013.



Close up: Hacksaw cut on 4" Awoba North West Well L & S flowlines at Boro. Picture was taken during Joint Investigation of 5th March 2013.



Close up: Missing flowline section on 4" Awoba North West Well L & S flowlines at Boro. Picture was taken during Joint Investigation of 5th March 2013.