



Overview: Part of spill impact on 8" Isimiri-Imogate pipeline right of way at Uzuaku. Picture was taken during Joint Investigation of 15<sup>th</sup> January 2013.



Close up: Illegal fitting on 8" Isimiri-Imogate pipeline at Uzuaku. Picture was taken during Joint Investigation of 15<sup>th</sup> January 2013.