



Overview: Part of spill impact on 24" Bomu-Bonny pipeline right of way at Mogho. Picture was taken during Joint Investigation of 10th January 2013.



Close up: Spill due to hacksaw cut on 24" Bomu-Bonny pipeline at Mogho. Picture was taken during Joint Investigation of 10th January 2013.