



Overview: Part of spill impact on 24" Nkpoku-Bomu pipeline right of way at Rumuoegwu-Eneka. Picture was taken during Joint Investigation of 10th July 2013.



Close up: Illegal fittings on 24" Nkpoku-Bomu pipeline at Rumuoegwu-Eneka. Picture was taken during Joint Investigation of 10th July 2013.