



Overview: Part of spill impact on 20" Otumara-Escravos pipeline right of way at Otumara. Picture was taken during Joint Investigation of 6th July 2013.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Otumara. Picture was taken during Joint Investigation of 6th July 2013.