



Overview: Part of spill impact on 12" Imo River2 – Ogale pipeline right of way at Umuololo/Owaza. Picture was taken during Joint Investigation of 24th July 2013.



Close up: Illegal fittings on 12" Imo River2 – Ogale pipeline at Umuololo/Owaza. Picture was taken during Joint Investigation of 24th July 2013.