



Overview: Part of spill impact on 24" Bomu-Bonny Trans Niger pipeline right of way at Owokiri-Bodo. Picture was taken during Joint Investigation of 13th July 2013.



Close up: Illegal fitting on 24" Bomu-Bonny Trans Niger pipeline at Owokiri-Bodo. Picture was taken during Joint Investigation of 13th July 2013.