



Overview Part of spill impact on 12" Imo River2 – Ogale pipeline right of way at Umuedeokwara /Odagwa. Picture was taken during Joint Investigation of 25<sup>th</sup> July 2013.



Close up: Illegal fitting on 12" Imo River2 – Ogale pipeline at Umuedeokwara /Odagwa. Picture was taken during Joint Investigation of 25<sup>th</sup> July 2013.