



Overview: Part of spill impact on 28" Bomu-Bonny TransNiger pipeline at Freetown. Picture was taken during Joint Investigation of 28<sup>th</sup> July 2013.



Close up: Illegal fitting on 28" Bomu-Bonny TransNiger pipeline at Freetown. Picture was taken during Joint Investigation of 28<sup>th</sup> July 2013.



Close up: Illegal fitting on 28" Bomu-Bonny TransNiger pipeline at Freetown. Picture was taken during Joint Investigation of 30<sup>th</sup> July 2013.