



Overview: Part of spill impact on 12" Oguta-Egbema pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 3rd July 2013.



Close up: Illegal fitting on 12" Oguta-Egbema pipeline at Obiakpu. Picture was taken during Joint Investigation of 3rd July 2013.