



Overview: Part of spill impact on 6" Obigbo North – Ogale pipeline right of way at Ogale. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2013.



Close up: Illegal fitting on 6" Obigbo North – Ogale pipeline at Ogale. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2013.