



Overview: Spill impact and fire on 28" Bomu-Bonny Trans Niger pipeline right of way at BodoWest. Picture was taken during reconnaissance visit of 19<sup>th</sup> June 2013.



Close up: Illegal fitting on 28" Bomu-Bonny Trans Niger pipeline at BodoWest. Picture was taken during Joint Investigation of 25<sup>th</sup> June 2013.