



Overview: Part of spill impact on 36" Rumuekpe-Nkpoku pipeline right of way at Omujiewhor-Ibaa. Picture was taken during Joint Investigation of 29<sup>th</sup> June 2013.



Close up: Illegal fitting on 36" Rumuekpe-Nkpoku pipeline at Omujiewhor-Ibaa. Picture was taken during Joint Investigation of 29<sup>th</sup> June 2013.