




Overview: Part of spill impact on 36" Nkpoku-Bomu pipeline right of way at Rumuowegwu. Picture was taken during Joint Investigation of 4th July 2013.



Close up: Illegal fittings on 36" Nkpoku-Bomu pipeline at Rumuowegwu. Picture was taken during Joint Investigation of 4th July 2013.