



Close up: Illegal fitting on 28" Bomu-Bonny Trans Niger pipeline at Bodo West.
Picture was taken during Joint Investigation of 28th June 2013.