



Overview: Part of spill impact on 10" Diebu Creek – Nun River pipeline right of way at Onyoma/Eniwari. Picture was taken during Joint Investigation of 22nd June 2013.



Close up: Hacksaw cut on 10" Diebu Creek – Nun River pipeline at Onyoma/Eniwari. Picture was taken during Joint Investigation of 22nd June 2013.