



Close up: Illegal fitting on 24" Nem,be creek pipeline at Adamakiri. Picture was taken during Joint Investigation of 3<sup>rd</sup> June 2013.