



Overview: Part of spill impact on 14" Okordia-Rumuekpe pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 7<sup>th</sup> June 2013.



Close up: Hacksaw cut on 14" Okordia-Rumuekpe pipeline at Ikarama. Picture was taken during Joint Investigation of 7<sup>th</sup> June 2013.