JOINT INVESTIGATION REPORT FOR INCIDENT NO: 947350 JIV report S/N: 1138 (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1. Spill incident Number: 947350 2.Type of incident* OIL SPILL 3. Name of Location 12" OGWIA - EGB+MA PIPELINE 4. Name of nearest community OBIAKPU 5. State: IMO 6. LGAEGBEMA 7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District NPE / EGBENTA. B. INCIDENT INFORMATION: 9. Details of incident tails of incident

a. Date of incident: 22" MARCH, 2013

b. Start date/time of investigation: 24" MARCH, 2013 / 9: 30 km/2

c. Investigation End date: 24" MARCH, 2018ctual investigation duration, days: d. Description of spill point environment ☐Firmed soil Loose soil Recently excavated area ☐Under water ☐ Swampy Exposed pipe surface □ Well Platform (on Water) □Drill Rig e. Description of leak point (tick as applicable); Drilled hole ☐Hack saw cut ☐ Tear (______), ☐Inward dent, Complete Rupture ☐Well head tampering ☐ Failed Weld-on illegal hot tap valve, ☐ Failed Clamp ☐Missing Pipeline/Flowline Crude oil theft (illegal bunkering) point, ☐ Third party tampering with Clamp ☐ Third party tampering with valve setting, ☐ Third party tampering with flange, ☐Saver-pit over flow, ☐Surge vessel overflow, ☐ Corrosion □Flare System/Bund wall failure □ Accidental 3rd party equipment ☐Bulging Outward Cold vent ☐ Valve Failure Com unit failure impact ☐Relief valve failure Others (specify)_ f. Incident caused by: Third party interference (Sabotago, crude theft□; Line theft□; Accidental 3rd party damage□) Others (including Mystery spills) ☐ Operational g. Spill point coordinates Measuring unit (M) Northing: 174 114.58

Page 1 of 9


OINT INVESTIGA	TION REPOR	T FOR INCIDE	NT NO: 95	17350 JIV	report S/N:	0033
C. RISK ASS	ESSMENT					0833
10.	Type of envi	ronment:				
V L	ınd □S	wamp 🔲	Water	Seasonal swamp	□Shoreline/Wa	aterfront
i.	Type of envir	onment to which				
	and 🗆 S	wamp 🔽	Water Water) □River (identify)_		
ii.	Weather cond	ition				
□Rai 11. Distan	n DSu ce from the near	nny action	Dry □we itat	et 🗖 Windy	□Hot	Cool
□ Di □ Bi □ Fi □ Fi □ Oi	overnment reservinking water soull the parea rmlands shift Farm/Pond shing net thers (specify).	urce	ed protected are	ea [M/L,m] [M^L,m] [12 ,m] [1, m] [M/L,m]		
12. Contai	nment measures	put in place;				
V⊒Bo □od		rench 🛂	Буке I	□Natural depression	n 🗖 Pit	
13. Any pi	ctures or video o	coverage?		PH [N	r]	
14. Was th	ere any disruptio	on to the investig	gation?	[Y] (N	ч	
If yes give brief	description:					
Mos	AN	LI CA	BLE			
D. TYPE/NUM	IBERS OF PRO	OPERTIES, IF	ANY, FOUND	WITHIN THE AR	EA OF SPRE	AD OF OIL
15. Struct	ures / Propertie	s				
S/N Type of	Structures	Description	Size	Number	Comm	ents
			-			<u> </u>
101	ueh	THIN	AR	en 0f	Trap	ACT

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 947350 JIV report S/N: 0038 16. Crops/Economic Trees S/N Type of crops Young Medium Matured Quantity Comments 17. Fish/Nets/Ponds Fish/Nets/Ponds Description Quantity/Size Comments FISH Mess CRUDE OIL WITH TRAPPED BY THE FUH NETS. SMALL SIZE SET ACPROIS THE STREAM 18. Others (Specify) i.e. Animal Traps

S/N	Others		Description		Quantity/Size	Comments
	3 . 1 6			4 6 2		
\mathcal{M}	ONE	Jal 1	1971M	-/1 K &	A 07	INITACI
/-	·				<u>-</u>	
		ļ				

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 12" OGNIA - EGBENNA PIPELINE AT OBJUKPU SHOWING
PUSITION OF DRILLED HOLE AT 12 O'CLOCK POSITION.



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 947350 JIV report S/N: 0038

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

<u> </u>		
S/N	Northing	Easting
		
		A ROOM
		—
	<u> </u>	
		- Inthi
		(8)
	 	X/
		
	 	
		Y/
		Na
	\ \ X	
	+	70
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
	- XX	
		Y
	A STATE OF S	
	Y / V	2
		70
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	N
	1 1 1 1 0 N	'
	1 / C S	
	1 1/0 (80	
		
	/	
/	1	
		
	 	

Total Area In	pacted (Ligh	t (mpact)
wp162	477942.06	174151.03
wp160	477948.19	174141.8
wp161	477951.24	174132.57
wp165	477951.23	174126.43
wp167	477949.29	174113.42
wp169	477941.95	174111.09
wp153	477938.87	174111.1
wp154	477935.8	174114.18
wp155	477938.89	174117.25
wp156	477941.99	174126.46
wp157	477942.02	174135.67
wp158	477938.98	174147.97
wp170	477932.83	174151.06
Impact On W	/ater	
wp171	477871.42	174115.09
wp172	477850.34	174116.13
wp173	477823.2	174130.33
wp174	477793.56	174124.69
wp175	477758.7	174092.75
wp176	477615.71	174090.67
wp177	477540.98	174059.98
wp178	477468.13	174082.53
wp179	477425.54	174075.43
wp180	477352.58	174097.35
wp181	477273.05	174106.53
wp182	477252.8	174072.51
wp183	477210.22	174036.18
wp184	477025.9	174077.1
wp185	476983.1	174072.09
wp186	476938.64	174086.7
wp187	476863.49	174087.33
wp188	476731.14	174131.16
wp189	476732.61	-
wp190	476864.09	
wp191	476939.47	
wp192	476983.52	
wp193	477026.1	
wp194	477209.38	
wp195	477250.3	
wp196	477271.59	
wp197	477354.46	-
wp198	477425.85	
wp199	477468.86	
wp200	477541.08	
wp201	477615.19	
wp202	477757.34	
wp203	477793.46	
wp204	477823.31	
wp205	477851.28	

wp206	477870.07	174119.26
wp207	477945.01	174161.64

.

JIV report S/N: UUJO
G. INCIDENT INFORMATION:
20. Impacted Area Details
• Total calculated area of impact
Impact within SPDC R.O.WYES
Impact outside SPDC R.O.W YES
21. Volume of oil recovered before completion of JIV (V _{recl}):
Recovered oil V _{recl} : 20 Barrels
20
 22. Computation of estimated residual volume on site a. Computation of estimated volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil
ii. Average Depth (m) of pool of free phase oil OO 6
iii. Emulsification factor: M/L
iv. Estimated Volume of pool of free phase oil. V _{pool} : 214.29 barrels
b. Computation of estimated volume of infiltrated oil in the soil (V _{inf}). 1. Estimated Volume of infiltrated oil at spill point (Vinf a) i. Area* (m²) of soil covered by the oil: ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: iii. Soil type:
ix. Estimated depth of infiltration around spill point: 1. 2005
x
Estimated Volume of infiltrated oil at spill point. V _{inf_a} : 2.42 barrels
2. Estimated Volume of infiltrated oil at second spill point [if applicable] (Vinf b)
i. Area* (m²) of soil covered by the oil:
ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: M/L
iii. Soil type: MIL iv. Pe (effective porosity of the soil). MIL
v. Cause of spill: MIL vi. Oil type: MIL
vii. Oil Residence time on site, day: NIL
viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: MiL
ix. Estimated depth of infiltration around spill point: MIL
Estimated Volume of infiltrated oil at spill point. V _{inf_b} : harrels

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

NT INVESTIGATION	REPORT FOR	INCIDENT NO:	94735	<u>ર્ડિ</u> JIV re	port S/N:	0033
		covered by the oil: _	•	 283	, -	
		pool of free phase oil			<u></u>	
	Soil type:	m) below ground surf	ace of infiltrat	tion of oil:_		
			9 %			
v.		osity of the soil)				
,	vi. Estima	nted Volume of infilu	ated oil. At V	inf:	0.0	7 ba
23. Computation	of estimated v	olume of oil on ope	n water bace	d on stand	 	
i. Total area	of oil on open wa	ater:	ii watei dase	u on stand	ard colorat	ion.
		oil on water based on	coloration (**Spill F Edition)	actors from U	SCG FOG (
	Thickness	Percentage		Edition)		
Dani-, 375-11.	(mm)	coverage	Volume (m3)	<u>'</u>		
Barely Visible	0.00004			_		
Silvery	0.00008			4		
Slight Color	0.00015	- 	<u> </u>	4		
Bright Color	0.0003			_		
Dull	0.001	Appla	CARI	<u>-1</u>		
Dark	0.002	1111	<u> </u>			
Black oil	0.1			4		
Emulsion (30% Oil)	1					
	Percent Total	100%				
iii.		me of oil on open wa	ter. V _{wat} :	M		Barrels
24. Calculation of	of evaporated vo	olume:				
	nated Volume a	vailable for evapor	ation within	surface are	ea: 216.	8
iii.	EstimatedVo	olume of evaporated	oil. V _{evap} :	72.	17	Barrels
Evap	oration Factors	(E-Factor) for SPD	C Crude oil		_	
Oil Type	Days on site	Bonny Light	Bonny Med	dium		-
Oil Residence time	< 1 day	10%		5%		
	1-7 days	25%		15%		
	> 7 days	40%	<u></u>	25%		
25 Not Estimat	od Cnillad Val	nano V (hible)	V ALLIA	** / / / / / / / / / / / / / / / / / /		111
	(bble) = 52	$\underline{\text{ume } V_{\text{Est}}(\text{bbls})} =$	V _{evap} (DDIS) +	V _{wat} (bbl	$s) + V_{inf}$ (t	$vois) + V_1$
$(bbls) + V_{rec.i}$	(0012) = 4	2.27+ MIL	+ 2.5	1 +2/	4-29+	20
	= 3	09.07 BARG	itis			
Estimated Reported V	olume** V _{ren} (bl	ols)= 215 p				 .

310 BARRELS.

Calculati	
sojiware i	ion of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using ving rules:
•	Any spill volume in excess of 1 bbl is rounded up to the next whole number.
•	Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.
	Examples: Calculated volume = 15.3 bbl Reported volume = 16 bbl Calculated volume = 0.35 bbl Reported volume = 0.4 bbl Calculated volume = 0.01 bbl Reported volume = 0.1 bbl.
Wherever steps for c	r this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropria column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.
26.	GENERAL STATUS OF THE SITE
	Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out
В. І	Investigation of the incident site showed that there is residual impact on site requiring further works
This re	REPRESENTATIVES eport was filled, agreed and signed on the 24/03/2013 by joint investigation natives from
This re	eport was filled, agreed and signed on the 24/03/2013 by joint investigation
This re represer	eport was filled, agreed and signed on the 74/03/2013 by joint investigation ntatives from
This rerepreser	eport was filled, agreed and signed on the 24/03/2013 by joint investigation natatives from Host Community:
This represer	eport was filled, agreed and signed on the 74/03/2013 by joint investigation ntatives from Host Community: Department of Petroleum Resources [DPR]: Output Department of Petroleum Resources [DPR]: Output
This represer	eport was filled, agreed and signed on the 14/03/2013 by joint investigation natatives from Host Community: 12 Department of Petroleum Resources [DPR]: 12 National Oil Spill Detection and Response Agency [NOSDRA]: 12
This represer	eport was filled, agreed and signed on the 24/03/2013 by joint investigation natatives from Host Community: D Department of Petroleum Resources [DPR]: D National Oil Spill Detection and Response Agency [NOSDRA]: D State Ministry of Environment [SME]: D
This represer	Peport was filled, agreed and signed on the 14/03/2013 by joint investigation intatives from Host Community: Department of Petroleum Resources [DPR]: National Oil Spill Detection and Response Agency [NOSDRA]: State Ministry of Environment [SME]: Nigeria Police Force [NPF]:
This represer	Poort was filled, agreed and signed on the 14/03/2013 by joint investigation intatives from Host Community: 12 Department of Petroleum Resources [DPR]: 12 National Oil Spill Detection and Response Agency [NOSDRA]: 12 State Ministry of Environment [SME]: 12 Nigeria Police Force [NPF]: 12 Shell Petroleum Development Company [SPDC]: 12

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 947350 JIV report S/N: 0038

28. Appendix 1: Overview sketch of the site

