JOINT INVESTIGATION REPORT FOR INCIDENT NO: 94-9945 JIV report S/N: 0203 (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 49945 2.Type of incident* OIL SPILL 1. Spill incident Number: 3. Name of Location OPUKUSHI WELL 34 T FLOWLING EGBEMO-ANGALABIRBAYELSA6. LGA EKEREMO

4. Name of nearest community 5. State: BAYELSA6. LGA EKEREMO 7. Type of Production facility/Installation FLOWLINES. Asset owner/District U10/G/PNWST **B. INCIDENT INFORMATION:** 9. Details of incident a. Date of incident: 26 TH MARCH, 2013
b. Start date/time of investigation: 2ND APRIL, 2013 AT 1354 HRS
c. Investigation End date: 4TH. APRIL Actual investigation duration, days: Two DAYS d. Description of spill point environment ☐Firmed soil Loose soil Recently excavated area Under water Swampy Exposed pipe surface □Well Platform (on Water) Drill Rig e. Description of leak point (tick as applicable); Hack saw cut Drilled hole ☐ Tear (), ☐Inward dent. Complete Rupture ☐ Well head tampering □ Failed Weld-on illegal hot tap valve, □ Failed Clamp ☐ Missing Pipeline/Flowline ☐Crude oil theft (illegal bunkering) point, ☐Third party tampering with Clamp Third party tampering with valve setting, Third party tampering with flange, Corrosion ☐Surge vessel overflow, ☐ Saver-pit over flow, ☐Bulging Outward Flare System/Bund wall failure Accidental 3rd party equipment □Valve Failure Com unit failure Cold vent impact DOthers (specify) PIN HOLE Relief valve failure f. Incident caused by: ☐ Third party interference (Sabotage☐; crude theft☐; Line theft☐; Accidental 3rd party damage☐) Doperational. Others (including Mystery spills)_____ g. Spill point coordinates Measuring unit (M Northing: Easting:

100860mN

37433 IME

| | | | | 1945)IV repo | | |
|---------------------------|--------------------------------|---------------------|-----------|-------------------|----------------|----------|
| . RISK ASSESS | | | | | | |
| 10. T | ype of environment: | | | | | |
| \square Land | Swamp | □Water | □Sea | asonal swamp□Si | horeline/Water | front |
| i. Ty | pe of environment to | which oil has | spread: | | | |
| \square Land | ☐ Swamp | W ater | □Ri | ver (identify) | | |
| ii. W | eather condition | | | | | |
| ☐Rain 11. Distance fro | Sunny om the nearest sensit | ☐Dry ive habitat | □Wet | □Windy | □Hot | □cool |
| | inds arm/Pond g net | lesignated prote | cted area | [,m] | | |
| 12. Containmen | nt measures put in pl | ace; | | | | |
| ☑Booms □Others: | | Dyke | □Nε | atural depression | □Pit | |
| 13. Any picture | es or video coverage | ? | | [X] [N] | | |
| 14. Was there a | any disruption to the | investigation? | | [Y] [N) | | |
| If yes give brief des | cription: | | | | | |
| MOT | AP | PLIC | A 13 | SLE | | |
| D. TYPE/NUMBE | RS OF PROPERT | IES, IF ANY, I | FOUND WI | THIN THE AREA | A OF SPREA | O OF OIL |
| 15. Structures | s / Properties | | | | | |
| | | | | | | |

| M I IIN | VESTIGATION REF | PORT FOR INCIDE | NT NO:! | 11420 | IV report S/N: | 0213 |
|----------------|---------------------|---------------------|---------|--|----------------|----------|
| | | | | | | |
| | 16. Crops/Economic | c Trees | | | | |
| S/N | Type of crops | Young | Medium | Matured | Quantity | Comments |
| 9 | PALM TREE | 28 | 22 | 54 | 104 | |
| 2 | RAFIA PALM | 14 | 17 | 123 | 154 | _ |
| | | | | | | |
| | | | / | | / | |
| | | / | | | | |
| L | | | | | / | |
| S/N | FISH NET | | / | Quantity/Size | Comments | , |
| 2 | FISH TRE | VP / | / | 1 \ | | |
| | /- | | | / | -/- | |
| -/- | / | | | | | |
| -/- | + <i>-</i> | | | | | |
| | 18. Others (Specify |) i.e. Animal Traps | 3 | | | |
| S/N | Others | Description | | Quantity/Size | Comments | |
| 1 | ING- W | JIHIN | ARC A | OF | IMPA | 10/ |

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

OPUKUSHI WELL 34 T FLOWLING

LEAK POINT AT

6 0° CLOCK POSITION

Page 3 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 949945 JIV report S/N: 923

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

| S/N | Northing | Easting |
|-----|---|---------|
| ı | 100862 | 374308 |
| 2 | 100862 | 374314 |
| 3 | 100771 | 374320 |
| 4 | | 374241 |
| 5 | 100651 | 373865 |
| 6 | 100610 | 373813 |
| 7 | 100715 | 274 279 |
| 78 | 100346 | 374 401 |
| 9 | 100872 | 374351 |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | 1 | |
| | | |
| | | |
| | | |
| | | |
| | / | |
| | | |
| | | |

| THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. |
|--|
| JOINT INVESTIGATION REPORT FOR INCIDENT NO: 94995 JIV report S/N: |
| G. INCIDENT INFORMATION: |
| 20. Impacted Area Details |
| 276112 112 |
| O 7 / 10 D |
| • Impact within SPDC R.O.W |
| • Impact outside SPDC R.O.W |
| Recovered oil V _{recj} : Recovered oil V _{recj} : Recovered oil V _{recj} : |
| 1412 |
| 22. Computation of estimated residual volume on site and Computation of estimated volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil NOT APPLICABLE ii. Average Depth (m) of pool of free phase oil NOT APPLICABLE iv. Estimated Volume of pool of free phase oil. Vpool: NIL barrels b. Computation of estimated volume of infiltrated oil in the soil (Vmt). 1. Estimated Volume of infiltrated oil at spill point (Vinf a) i. Area* (m²) of soil covered by the oil: NIL ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: NOT APPLICABLE v. Cause of spill: APPLICABLE vii. Oil Residence time on site, day: NOT APPLICABLE viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: APPLICABLE viii. Estimated depth of infiltration around spill point: NOT APPLICABLE x. Estimated Volume of infiltrated oil at spill point. Vmf, a: NIL barrels |
| 2. Estimated Volume of infiltrated oil at second spill point [if applicable] (Vinf b) |
| i. Area* (m²) of soil covered by the oil: NIL ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: NOT APPLICABLE iii. Soil type: APPLICABLEIV. Pe (effective porosity of the soil). NOT APPLICABLE v. Cause of spill: APPLICABLEVI. Oil type: APPLICABLE vii. Oil Residence time on site, day: NOT APPLICABLE NOT |
| ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: NOT APPLICABLE |
| iii. Soil type: APPLICABLEIV. Pe (effective porosity of the soil). NOT APPLICABLE v. Cause of spill: APPLICABLEVI. Oil type: APPLICABLE |
| v. Cause of spill: APPLICABLEVI. Oil type: APPLICABLE vii. Oil Residence time on site, day: NOT APPLICABLE NOT |
| Aparica Caraca |
| viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: APPLICABLE ix. Estimated depth of infiltration around spill point: NoT APPLICABLE |

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

Estimated Volume of infiltrated oil at spill point. V_{inf_h}:

| THE SHELL | . PEINULEU | IN DEVELORI | HEINT COMPAN | I OI II | HOLNIA LIMITEL | . . | |
|---|---|--------------------|------------------------------------|---------------|----------------|------------|--|
| JOINT INVESTIGATION F | REPORT FOR |) _:INCIDENT NO | 749945 | ∠ Z JIV re | port S/N: | | |
| | | covered by the oi | | | 20203 | | |
| 18 ii. A | | _ | | nil: | NIL | | |
| | Area (m²) of the pool of free phase oil in touch with soil: | | | | | | |
| Lil iv. s | Soil type: NOT APPLICABLE | | | | | | |
| SE V | Pe (effective porosity of the soil). NOT APPILICABLE | | | | | | |
| · | i. Estim | ated Volume of in | filtrated oil. At V _{int} | ı: | NIL | barrels | |
| 23. Computation of estimated volume of oil on open water based on standard coloration. i. Total area of oil on open water: 27,643 m² ii. Table of average depth of oil on water based on coloration (**Spill Factors from USCG FOG (2000) | | | | | | | |
| | Thickness | Percentage | | Edition) | | | |
| | (mm) | coverage | Volume (m3) | | | | |
| Barely Visible | 0.00004 | 10% | 0.000 110520 | | | | |
| Silvery | 0.00008 | | | | | | |
| Slight Color | 0.00015 | 15% | 0.0006219675 | | | | |
| Bright Color | 0.0003 | | | | | | |
| Dull | 0.001 | 10 6/0 | 00027643 | | | | |
| Dark | 0.002 | | | | | | |
| Black oil | 0.1 | | | | | | |
| Emulsion (30% Oil) | 1 | 65% | 5.390385 | | | | |
| مم | Percent Total | 100% | | | | | |
| iii. | Estimated Vol | ume of oil on ope | n water. V _{wat} : | | 33.73 Barr | els | |
| 24. Calculation of | of evaporated v | olume: | | | | • | |
| | | | | | 27 27 1 | 2010 | |

- i. Estimated Volume available for evaporation within surface area: 33.93 BBLs
- ii. E-Factor: 15%

iii. EstimatedVolume of evaporated oil. V_{evap}: 5.99 Barrels

| Evap | oration Factors | (E-Factor) for SP | DC Crude oil |
|--------------------|-----------------|-------------------|--------------|
| Oil Type | Days on site | Bonny Light | Bonny Medium |
| Oil Residence time | < 1 day | 10% | 5% |
| | 1-7 days | 25% | 15% |
| | > 7 days | 40% | 25% |

25. Net Estimated Spilled Volume
$$V_{Est}(bbls) = V_{evap}(bbls) + V_{wat} (bbls) + V_{inf} (bbls) + V_{pool} (bbls) + V_{recl} (bbls) = 599 + 33.93 + NIL + NIL + NIL = 39.9288L5$$
Estimated Reported Volume** $V_{reg}(bbls) = 4088L5$

| | HE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. |
|-------------|--|
| OINT INVEST | IGATION REPORT FOR INCIDENT NO: 94-9945 JIV report 6/N: 02:3 |
| | of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation site; Conversion of m^3 to barrels is Volume ($m3$) x 6.29; **Round up estimated volume to next whole number using a rules: |
| | y spill volume in excess of 1 bbl is rounded up to the next whole number. |
| • An | ny spill volume in less than — I-bbl — is rounded up to the next 0.1 bbl. |
| Ex | Calculated volume = 15.3 bbl Reported volume = 16 bbl Calculated volume = 0.35 bbl Reported volume = 0.4 bbl Calculated volume = 0.01 bbl Reported volume = 0.1 bbl. |
| | is estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriat umn estimation; record the calculation in a plain sheet of paper and attach to the JIV report. |
| 26. G | ENERAL STATUS OF THE SITE |
| 1 | nt investigation of the incident site found that there is no residual impact after the initial sponse and therefore recommend that the site be closed out \Box |
| l . | vestigation of the incident site showed that there is residual impact on site requiring further orks |
| | EPRESENTATIVES ort was filled, agreed and signed on the 4 / 4 /2012 by joint investigation |
| representa | atives from |
| • H | ost Community: |
| • D | epartment of Petroleum Resources [DPR]: |
| • N | ational Oil Spill Detection and Response Agency [NOSDRA]: 🖫 |
| • St | tate Ministry of Environment [SME]: |
| | igeria Police Force [NPF]: |
| | hell Petroleum Development Company [SPDC]: 🖾 |
| | |
| • Si | ignatories agree with reported findings: |
| • Se | eparate DPR form has been filled out with same findings 🖫 |
| | Tick as applicable |

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 94945 JIV report S/N: 0203

28. Appendix 1: Overview sketch of the site

Location: OPUKUSHI WELL 34T FLOWLING SPILL SITE SPILLED CRUDEOIL SECTION FEMULSIFIED HEAVIL LEAK POINT WELL HEAD SLOT BOOM