



Overview: Part of spill impact on 24" Nembe Creek Trunkline right of way at Aberedo-A. Picture was taken during Joint Investigation of 2nd April 2013.



Close up: Illegal fittings on 24" Nembe Creek Trunkline at Aberedo-A. Picture was taken during Joint Investigation of 3rd April 2013.