



Overview: Part of spill impact on 14" Okordia-Rumuekpe pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 15th March 2013.



Close up: Location of corrosion point on 14" Okordia-Rumuekpe pipeline at Ikarama. Picture was taken during Joint Investigation of 16th March 2013.