



Overview: Part of spill impact on 30" Nembe Creek pipeline right of way at Bille. Picture was taken during Joint Investigation of 14<sup>th</sup> March 2013.



Close up: Illegal fitting on 30" Nembe Creek pipeline at Bille. Picture was taken during Joint Investigation of 14<sup>th</sup> March 2013.