



Overview: Part of spill impact on 12" Imo River2 – Ogale pipeline right of way at KomKom. Picture was taken during Joint Investigation of 30th March 2013.



Close up: Illegal fitting on 12" Imo River2 – Ogale pipeline at KomKom. Picture was taken during Joint Investigation of 30th March 2013.