



Overview: Part of spill impact on 20" Otumara-Escravos trunkline right of way at Ugbokodo. Picture was taken during Joint Investigation of 7th June 2013.



Close up: Illegal fitting on 20" Otumara-Escravos trunkline at Ugbokodo. Picture was taken during Joint Investigation of 7th June 2013.