



Overview: Part of spill impact on 12" Adibawa-Okordia pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 30th May 2013.



Close up: Spill due to hacksaw cut on 12" Adibawa-Okordia pipeline at Ikarama. Picture was taken during Joint Investigation of 30th May 2013.