



Overview: Part of spill impact on 8" Ubie-Ukpeliede pipeline right of way at Idu-Ekpeye . Picture was taken during Joint Investigation of 17th May 2013.



Close up: Hacksaw cut on 8" Ubie-Ukpeliede pipeline at Idu-Ekpeye . Picture was taken during Joint Investigation of 17th May 2013.



Close up: Chiseled clamp nuts on 8" Ubie-Ukpeliede pipeline at Idu-Ekpeye . Picture was taken during Joint Investigation of 17th May 2013.



Close up: Chisel marks on clamp nuts on 8" Ubie-Ukpeliede pipeline at Idu-Ekpeye . Picture was taken during Joint Investigation of 17th May 2013.