



Overview: Part of spill impact on 30" Nembe Creek pipeline right of way at Boro (Kula). Picture was taken during Joint Investigation of 14<sup>th</sup> May 2013.



Close up: Illegal fitting on 30" Nembe Creek pipeline at Boro (Kula). Picture was taken during Joint Investigation of 14<sup>th</sup> May 2013.