



Overview: Part of spill impact on 36" Nkpoku-Bomu pipeline right of way at Elenwo. Picture was taken during Joint Investigation of 10th May 2013.



Close up: Illegal fittings on 36" Nkpoku-Bomu pipeline at Elenwo. Picture was taken during Joint Investigation of 10th May 2013.



Close up: Illegal fittings on 36" Nkpoku-Bomu pipeline at Eelenwo. Picture was taken during Joint Investigation of 12th May 2013.