



Overview: Part of spill impact on 12" Imo River2 pipeline right of way at Umuedeokwara. Picture was taken during Joint Investigation of 24th May 2013.



Close up: Illegal fitting on 12" Imo River2 pipeline at Umuedeokwara. Picture was taken during Joint Investigation of 24th May 2013.